- temperature: °F = 32+ (°C x 9/5)
- pressure: psi = bar x 14.5

Support

Ask for support

In case of malfunction or fault and requests for assistance, contact SELPRO Srl or the distributor in your country.

How to return the product

If necessary, **ship the product at your own expense and in its original packaging** to the local distributor or directly to SELPRO Srl.

Zone distributor	Customer support service	
Note distributor information here:	SELPRO Srl Via Piamarta, 5/11 25021 Bagnolo Mella (BS) Italy	info@selpro.it www.selpro.it +39 (0)30 6821611

Warranty

To know the warranty terms, exclusions, warranty forfeiture, and how to apply the warranty, please refer to the enclosed sheet.